

[Skip to content](#)



# Product Safety Recalls Australia

[Advanced recall search](#)

## Recall categories

- [+ Agricultural & veterinary](#)
- [+ Beauty, health](#)
- [+ Cars, boats, bikes](#)
- [★ Electrical](#)
- [+ Fashion & clothing](#)
- [+ Food & groceries](#)
- [★ Gas](#)
- [+ Hobbies, sporting, recreation](#)
- [+ Home & garden](#)
- [+ IT, phones, multimedia](#)
- [+ Industrial, business](#)
  - [★ Machinery](#)
  - [★ Office](#)
  - [★ Safety equipment](#)
  - [★ Tools of trade](#)
  - [★ Trade supplies, building materials](#)
- [+ Kids](#)

## Site features

- [+ For suppliers conducting product safety recalls](#)
- [★ Advanced recall search](#)
- [+ Subscribe to email alerts & RSS](#)
- [★ FAQs](#)
- [★ Hot topics](#)
- [★ Recalls - last 30 days](#)
- [★ Report an Unsafe Product](#)
- [★ Useful Links](#)
- [★ Contact Us](#)
  
- [★ Login](#)

[Home](#) → [Recall categories](#) → [Industrial, business](#) → [Safety equipment](#) → [BFI and BFI-HP—4.5kg and 9.0kg ABE Dry Powder Extinguishers \(with External Nut\)](#)

## BFI and BFI-HP—4.5kg and 9.0kg ABE Dry Powder Extinguishers (with External Nut)

*PRA number:*  
*Date created:* 21<sup>st</sup> February 2011



### Product information

#### Product description

4.5kg and 9.0kg ABE dry chemical fire extinguishers (with external nut)

#### Identifying features

4.5kg ABE - Model No: FP45ABE  
Serial Nos.:  
CR680930-CR682129  
CR684060-CR685259  
SA110012-SA111211  
SA116842-SA118047  
SA495196-SA495315  
SA504222-SA505421  
SA727180-SA728499  
SA761291-SA761380  
SA786140-SA786859  
SA962982-SA964181  
SB044562-SB045761

9.0kg ABE - Model No: FP90ABE  
Serial Nos.:  
CR683230-CR684059  
SA035001-SA035830  
SA108103-SA108932  
SA118043-SA118872  
SA244751-SA245580  
SA494318-SA495195  
SA503392-SA504221  
SA506823-SA507652  
SA726175-SA727179  
SA758441-SA759312  
SA764397-SA785724  
SA964182-SA965011  
SB053099-SB053430

#### What are the hazards?

The fire extinguishers may fail to operate due to damage caused to their spindle tops during use.

#### What are the defects?

A proportion of these extinguishers are fitted with valve stems longer than standard, which may result in operational wear to their spindle tops. The hazard only applies to fire extinguishers that have been subjected to conditions of excessive vibration, high temperatures and aggressive handling.

#### Where the product was sold

- ★ Nationally

#### Supplier

Bulbeck Fire Industries

#### Supplier's web site

<http://www.bulbeck.com.au>

#### What should consumers do?

Return product to place of purchase or direct to Bulbeck Fire Industries for a new replacement extinguisher.

For customer service, call: or go to the following website:  
<http://www.bulbeckfire.com.au/page10577/contact.aspx>

[Print](#)



### Related Topics

- ★ [Chubb Fire & Security Pty Ltd —Chubb and Flameguard 1.5kg, 2.3kg, 2.5kg and 4.5kg dry powder fire extinguishers](#)
- ★ [Chubb Fire & Security Pty Ltd—Chubb, Quell, Fire Smart, Motorcraft and Flameguard 1 kg fire extinguishers](#)